

## **Annual Notification of AHERA Activities**

### **Bishop Watterson High School**

Date: October 6, 2020

To: All School District Employees, Parents, and Students

From: Columbus Diocese LEA

Subject: Annual Notification of AHERA Activities for Bishop Watterson High School

The following activities took place between September 1, 2019 and August 31, 2020 fulfilling our requirements under 40CFR 763 (AHERA)

- An AHERA 3 year re-inspection will be scheduled for 2021
- A 6 month Surveillance inspection was performed Dec. 2019
- A 6 month Surveillance inspection was performed June 2020
- A 6 month Surveillance inspection is scheduled for Dec. 2020
- A 6 month Surveillance inspection is scheduled for June 2021
- The following work was performed by North American Environmental between June 1, 2020 and August 1, 2020
  - 1- Remove and dispose of approximately 40 linear feet of damaged asbestos containing pipe insulation located in the closet of Room 13B, approximately 5 linear feet of damaged asbestos containing pipe insulation located in the basement hallway off the copying room, approximately 30 linear feet of damaged asbestos containing pipe insulation and approximately 15 damaged asbestos containing mudded joint packings located within the pipe chase off the 1<sup>st</sup> floor girls restroom, decontaminate approximately 100 square feet of asbestos containing debris located within the pipe chase of the 1<sup>st</sup> floor girls restroom and approximately 25 square feet of damaged asbestos containing floor tile/mastic located in the janitor closet next to the 1<sup>st</sup> floor girls restroom. Once removed NAES will apply re-wettable to any exposed asbestos containing pipe insulation.
  - 2- Remove and dispose of approximately 50 linear feet of damaged asbestos containing pipe insulation and approximately 15 damaged

asbestos containing mudded joint packings located within the tunnel off the basement bookroom storage area, 2 damaged asbestos containing mudded joint packings and approximately 20 linear feet of damaged asbestos containing pipe insulation located within the basement boiler room, approximately 15 linear feet of damaged asbestos containing pipe insulation within the maintenance room and 2 damaged asbestos containing mudded joint packings located within the 2 mechanical rooms off the north gym balcony. Once removed NAES will apply re-wettable to any exposed asbestos containing pipe insulation.

- There were no major or minor fiber release episodes recorded during the 2019-2020 school year.
- Should you have any questions regarding the information included in this notification, or wish to review the school's Asbestos Management Plan, please contact the Principal, Deacon Christopher Campbell at 614-268-8671.